

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEURON						API Number 30-025-35561				
Property Name VACUUM GRAYBURG SAN ANDRES UNIT						Well No. 135				
Surface Location										
UL - Lot G	Section 1	Township 19S	Range 34E	☒	Feet from 2535	N/S Line FNL	Feet From 1930	E/W Line FEL	County LEA	
Well Status										
TAPED WELL YES ☐ NO ☐		SHUT-IN YES ☐ NO ☐		☒ INJECTOR ☐ SWD		PRODUCER OIL ☐ GAS ☐		DATE 5/5/14		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			225	1910
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	☒ / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	☒ / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	☒ / N	
Water	Y / N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

① gas pressure bled down to zero psi verified
24 hours later.
FOR RECORD ONLY

B8 8/08/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/21/14	Phone: 575 942-3526		
Witness:			

AUG 19 2014

