

JUL 31 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-02256	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 025	

Surface Location									
BL - Lot L	Section 1	Township 18S	Range 34E	✓	Feet from 1980	N/S Line FSL	Feet From 660	E/W Line FWL	County LEA

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OH	PRODUCER GAS	DATE 5/5/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Currently down for wellhead failure, unable to acquire pressure readings. (Oil well)

~~Failed~~

B8 8/08/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/23/14	Phone: 575 942-3526		
Witness:			

AUG 19 2014

