

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 25 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-25813
Property Name CENTRAL VACUUM UNIT	Well No. 25

Surface Location

UL - Lot K	Section 25	Township 17S	Range 34E	Feet from 1330	N/S Line FSL	Feet From 1504	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR (INJ)	SWD	PRODUCER OIL	GAS	DATE 5/5/14
------------------	----	----------------	----	--------------------------	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod C/sng	(E) Tubing
Pressure	0	375		-1075	1811
Flow Characteristics					
Puff	Y / N	(Y) / N	Y / N	(Y) / N	CO2 X
Steady Flow	Y / N	(Y) / N	Y / N	(Y) / N	WTR
Surges	Y / N	(Y) / N	Y / N	(Y) / N	GAS
Down to nothing	Y / N	(Y) / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / N	(Y) / N	Y / N	(Y) / N	Injected for
Water	Y / N	(Y) / N	Y / N	(Y) / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(B) Gas pressure bled down to zero.


(D) CO2 pressure, would not bleed down:

FOR RECORD ONLY

> Failure

Letter of Violation 8/19/2014
SAD/SED

BS 8/11/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McWen	Entered into RBDMS
Title: Sub Surface Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 7/24/14	Phone: 575-942-3526
Witness:	

AUG 20 2014

