

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-10312
Property Name RE Cole	Well No. 3

2. Surface Location

UL - Lot M	Section 16	Township 22S	Range 37E	Feet from 900	N.S. Line FSL	Feet from 990	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	-------------------------	-------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING SLIPS LAG	DATE 5/19/14
-------------------------	---------	-------------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0			0	1000
Flow Characteristics					
Puff	Y / ☒	Y / N	Y / N	Y / ☒	
Steady Flow	Y / ☒	Y / N	Y / N	Y / ☒	
Surges	Y / ☒	Y / N	Y / N	Y / ☒	
Down to nothing	☒ / N	Y / N	Y / N	☒ / N	
Gas or Oil	Y / ☒	Y / N	Y / N	Y / ☒	
Water	Y / ☒	Y / N	Y / N	Y / ☒	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD ONLY

B8 8/16/2014

Signature: Justin Hobbs	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: kuuv@chevron.com	
Date: 5/19/14	Phone: 575-631-4228
Witness:	

AUG 20 2014