

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON		API Number 30-025-29988	
Property Name NEW MEXICO 2 STATE NCT-1		Well No. 001	

2. Surface Location

UL - Lot C	Section 2	Township 18S	Range 34E	✓	Feet from 660	N/S Line FNL	Feet from 2600	E/W Line FNL	County LEA
----------------------	---------------------	------------------------	---------------------	----------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

2200

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 5/5/14
------------------	----	----------------	----	-----	-----------------	------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		60	110
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / 0	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	0 / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / 0	GAS ____
Down to nothing	Y / N	Y / N	Y / N	0 / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / 0	Injected for
Water	Y / N	Y / N	Y / N	0 / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) Packer fluid bled down to zero, Came back 24 hours later pressure was at 40 psi. Bled down to zero still packer fluid. Came back 24 hours after that + pressure was at zero.

OR RECORD ONLY

BS 8/14/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McGwen		Entered into RBDMS	
Title: Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 6/26/14	Phone: 575-942-3526		
Witness:			

AUG 20 2014

h. ou