

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 11 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHAPARRAL ENERGY	API Number 30-025-12212
Property Name WEST DOLLARIDE QUEEN SAND UNIT	Well No. 1

7. Surface Location

UL - Lot	Section 19	Township 24-S	Range 38-E	Feet from 330	N/S Line FSL	Feet From 2310 FFL	E/W Line FEL	County LRA
----------	----------------------	-------------------------	----------------------	-------------------------	------------------------	------------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 6-25-14
-------------	----------------	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	0 / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

FOR RECORD

BS 7/18/2014

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address: William.dunlap@chaparralenergy.com	
Date:	Phone: 432-561-9462
Witness:	

AUG 22 2014