

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 11 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHAPARRAL ENERGY LLC	API Number 30-025-12285
Property Name WEST DOLLARHIDE QUEEN SAND UNIT	Well No. 33

2. Surface Location

UL - Lot	Section 31	Township 24S	Range 38-E	☒	Feet from 1750	N/S Line PWL	Feet From 2310	E/W Line PWL	County LCA
----------	----------------------	------------------------	----------------------	-------------------------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 6-25-14
-------------	----------------	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0			260	260
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	☒ Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	☒ Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ☒	FRESH	SALTY	SULFUR	BLACK
---	-------	-------	--------	-------

Remarks:

Well FAILED Bradenhead TEST. Well IS COMMERCIAL. Well SHUT IN

FOR RECORD ONLY

> Failed FT After Repairs Witnessed AD 8/22/2014
By MARK Whitaker 8/5/14

BS 7/18/2014

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address: William.dunlap@chaparralenergy.com	
Date:	Phone: 432-561-9462
Witness:	

AUG 22 2014