

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 11 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>CHAPARRAL ENERGY LLC</i>	API Number <i>30-025-30192</i> ✓
Property Name <i>West DALLAR Hide Queen SAND UNIT</i>	Well No. <i>111</i> ✓

7. Surface Location

UL - Lot	Section	Township	Range	✓	Feet from	N/S Line	Feet From	E/W Line	County
	<i>29</i>	<i>24-S</i>	<i>38-E</i>		<i>1830</i>	<i>RSL</i>	<i>460</i>	<i>PWL</i>	<i>LeA</i>

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
		<i>1-1</i>	<i>6-25-14</i>

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	<i>0</i>			<i>0</i>	<i>1020</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	<i>(2)</i>
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

DID A Pressure CHART on well.

FOR RECORD ONLY

BS 7/18/2014

Signature: <i>William Dunlap</i>	OIL CONSERVATION DIVISION
Printed name: <i>William Dunlap</i>	Entered into RBDMS
Title: <i>Prod. Tech</i>	Re-test
E-mail Address: <i>William.dunlap@chaparralenergy.com</i>	
Date:	Phone: <i>432-561-9462</i>
Witness:	

AUG 22 2014