

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

JUL 11 2014

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	APPROVED 30-025-30196
Property Name West Dollarhide Queen SAND UNIT	Well No. 108

7. Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
	29	24-S	38-E	-	2310	FNL	380	FWL	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE 6-25-14
-------------	----------------	-----------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

ON RECORD ONLY

BS 7/18/2014

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address: William.dunlap@chaparralenergy.com	
Date:	Phone: 432-561-9462
	Witness:

AUG 22 2014