

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

JUL 11 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	API Number 30-025-30290 ✓
Property Name West DOLLAR Hide Queen SAND unit	Well No. 128 ✓

Surface Location

UL - Lot	Section 19	Township 24-S	Range 38-E	Feet from 660	N/S Line PSL	Feet From 2175	E/W Line PWL	County Lea
----------	----------------------	-------------------------	----------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN ✓	PRODUCING	DATE 6-25-4
-------------	------------------	-----------	-----------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ✓	FRESH	SALTY	SULFUR	BLACK
---------	-------	-------	--------	-------

Remarks:

OK RECORD ONLY

BS 7/18/2014

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech.	Re-test
E-mail Address: William.dunlap@chaparralenergy.com	
Date:	Phone: 432-561-9462
	Witness:

AUG 22 2014