Submit One Copy To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-025-06204
District IIIOIL CONSERVATION DIVISIONDistrict III1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NIM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	0. State Off & Gas Lease No. 015823
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Eunice Monument Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other WOBBS OCD	8. Well Number 10 .
	9. OGRID Number
Burgundy Oil & Gas of New Mexico, Inc. 3. Address of Operator AUG 21 2014	003044 10. Pool name or Wildcat
401 W. Texas Ave., Suite 1003 Mildiand, TX 79701	Eunice Monument; Grayburg – San Andres
4. Well Location RECEIVED	
Unit Letter <u>C</u> : <u>330</u> feet from the <u>North</u> line and <u>1650</u> feet from the <u>West</u> line	
Section <u>21</u> Township <u>20S</u> Range <u>37E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3521' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
' PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING ' TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
OTHER:	
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. AII INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
When all work has been completed, votorn this form to the appropriate District office to schedule an inspection.	
SIGNATURE	tantDATE08/20/2014
TYPE OR PRINT NAMECindy K. CampbellE-MAIL:ccampbell.bogi@	Datt.net PHONE: _432-684-4033
TYPE OR PRINT NAME _ Gindy K. Campbell E-MAIL:ccampbell.bogi@att.net PHONE: _432-684-403 ~ N · For State Use Only APPROVED BY:	
AUG 27 2014	