

AUG 07 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Merit energy Company	* API Number 30-025-28515
Property Name State A Alc 1	Well No. 120

7. Surface Location

UL - Lot C	Section 10	Township 23 S	Range 36 E	NMPM	Feet from 25	N/S Line N	Feet from 1345	E/W Line W	County Lea
---------------	---------------	------------------	---------------	------	-----------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN Yes	PRODUCING No	DATE 7-9-14	MP & MB Test
-------------	----------------	-----------------	----------------	--------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Csg	(E) Tubing
Pressure	0	0	0	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME \_\_\_ WTR, \_\_\_ GAS, \_\_\_ CO2

MP & MB Test 7-9-14  
Vista Service pump truck csg was loaded pressure to 560# No  
bleed off in 31 mins. End press 560#. bleed back into truck  
Rigged down

FOR RECORD ONLY

BS 8/12/2014

Signature:	OIL CONSERVATION DIVISION
Printed name: Gonzalo Luna	Entered into RBDMS
Title: Lead Pumper	Re-test
E-mail Address: Gonzalo.Luna@meritenergy.com	
Date: 7-9-14	Phone: 575-390-8937
Witness:	

SE. 03 2014