

AUG 25 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cross Border Res. Inc	API Number 30005205320000
Property Name Hahn Federal	Well No. #5

Surface Location

UL - Lot	Section 27	Township 7S	Range 31E	Feet from	NS Line	Feet from	E/W Line	County
----------	----------------------	-----------------------	---------------------	-----------	---------	-----------	----------	--------

Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES	NO	YES	NO	
		INJ	OIL	
		SWD	GAS	

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Casing	(E) Tubing
Pressure	NONE	0	0	0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 —
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR —
Surges	Y / N	Y / N	Y / N	Y / N	GAS —
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY
Need Sign

BS 9/3/2014

Signature: <i>Michael Williams</i>	OIL CONSERVATION DIVISION
Printed name: Mike Williams	Entered into RBDMS
Title: Construction foreman	Re-test
E-mail Address: mwilliams@rcdmountainresources.com	
Date: 8/19/2014	
Phone:	
Witness: <i>[Signature]</i>	

SEP 05 2014