

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <i>E.G.L. Resources, Inc.</i>	API Number <i>30-025-00048</i> ✓
Property Name <i>Moore Devonian Coop SWD</i>	Well No. <i>3</i> ✓

7. Surface Location

UL - Lot	Section <i>14</i>	Township <i>11</i>	Range <i>32</i>	Feet from <i>1980</i>	N/S Line <i>S</i>	Feet From <i>660</i>	E/W Line <i>E</i>	County <i>Lea</i>
----------	----------------------	-----------------------	--------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES ☒ NO	SHUT-IN YES ☒ NO	INJ INJECTOR ☒ SWD	OIL PRODUCER GAS	DATE <i>8-27-14</i>
--	--	--	---------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<i>0 psi</i>	<i>260 psi</i>		<i>390 psi</i>	<i>14 psi</i>
Flow Characteristics					
Puff	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	CO2 —
Steady Flow	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	WTR —
Surges	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	GAS —
Down to nothing	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Type of Fluid
Gas or Oil	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Injected for
Water	Y/N ☒	Y/N ☒	Y/N	Y/N ☒	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

D - Surged off ± 1/2 bbl water, bled down to trickle

FOR RECORD ONLY

B8 9/3/2014

Signature: <i>David Lovelady</i>	OIL CONSERVATION DIVISION
Printed name: <i>David Lovelady</i>	Entered into RBDMS
Title: <i>Dr. Sept</i>	Re-test
E-mail Address: <i>david@eg/resources.com</i>	
Date: <i>8-27-14</i>	Phone: <i>432-813-1084</i>
Witness:	

SEP 05 2014