

AUG 29 2014

State of New Mexico

JUL 31 2014

Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

RECEIVED

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-27913-	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 47	

Surface Location

UL - Lot 0	Section 25	Township 17S	Range 34E	-	Feet from 990	N/S Line FSL	Feet From 2308	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	----------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	PRODUCER OIL ✓	GAS GAS	DATE 5/5/14
------------------	----	----------------	----	------------	------------	--------------------------	------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	5	25		70	220
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ____
Surges	Y / N	Y / N	Y / N	Y / N	GAS ____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid Injected for Waterflood if applies.
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.


(A) gas pressure blew down immediately.

(B) packer fluid blew down to zero.

Verified both pressures were still at zero 24 hours later.

FOR RECORD ONLY

BS 9/3/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lhb@chevron.com			
Date: 7/22/14	Phone: 575-942-3526		
Witness:			

SEP 08 2014