

JUL 31 2014

AUG 29 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-30969	
Property Name VACUUM GLORIETTA WEST UNIT		Well No. 75	

Surface Location

U/L - Lot H	Section 36	Township 17S	Range 34E	Feet From 2310	N/S Line FNL	Feet From 990	E/W Line FEL	County LEA
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

TA'D WELL ☒ YES	NO	SHUT-IN YES	NO	INJ INJ	SWD SWD	OIL OIL	PRODUCER GAS	DATE 5/5/14
--	----	----------------	----	------------	------------	------------	-----------------	-----------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	10	250		20	200
Flow Characteristics					
Puff	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	CO2 ___
Steady Flow	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	WTR ___
Surges	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	GAS ___
Down to nothing	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	Type of Fluid
Gas or Oil	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	Injected for
Water	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	Waterflood d applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(A) Small amount of gas pressure bled down immediately
(B) took 10 minutes for gas pressure to bleed down. Verified 24 hours later that pressure was still at zero.

FOR RECORD ONLY

BS 9/3/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 7/23/14	Phone: 575-942-3526		
Witness:			

SEP 08 2014

