

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

AUG 29 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON					API Number 30,025-36018				
Property Name TRINITY BURRUS ABO UNIT					Well No. 013				
Surface Location									
BL - Lot H	Section 22	Township 12S	Range 38E	Feet from ✓	N/S Line FWL	Feet From 090	E/W Line FEL	County LEA	
Well Status									
TAD WELL YES		SHUT-IN NO		INJECTOR INJ ✓		PRODUCER OIL		DATE 7/16/14	

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Injection system currently down for facility repairs.

FOR RECORD ONLY

B8 9/2/2014

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McEwen		Entered into RBDMS	
Title: Production Specialist		Re-test	
E-mail Address: lnnb@chevron.com			
Date: 8/18/14	Phone: 575-942-3526		
Witness:			

SEP 08 2014

