

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 29 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON		API Number 30-025-35038
Property Name TRINITY BURRUS ABO UNIT		Well No. 011

Surface Location

UL - Lot K	Section 22	Township 12S	Range 38E	Feet from 1650	NS Line FSL	Feet from 2310	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	-----------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 7/16/14
------------------	----	-----------------------	----	------------------------	-----	-----	-----------------	------------------------

OBSERVED DATA


	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csing	(E)Tubing
Pressure	0	0		0	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Injection system down for facility repairs

FOR RECORD ONLY

B8 9/3/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McEwen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 8/18/14	Phone: 575-942-3526
Witness:	

SEP 08 2014

