

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CAMBRIAN MANAGEMENT	API Number 30-005-20228
Property Name DAVIS N	Well No. #1

2. Surface Location									
UL - Lot F	Section 18	Township 8S	Range 33E 32E		Feet from	N/S Line	Feet From	E/W Line	County

Well Status									
YES	TA'D WELL. NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER	GAS	DATE 8-26-14

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 9/6/2014

Signature: Eddie J. Jaramillo	OIL CONSERVATION DIVISION
Printed name: Eddie J. Jaramillo	Entered into RBDMS
Title: PUMPER	Re-test
E-mail Address:	
Date: 8-26-14	Phone: (575) 369-6134
Witness:	

SEP 11 2014