

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

4

BRADENHEAD TEST REPORT

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-37451
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 711

2. Surface Location

UL - Lot C	Section 29	Township 18-S	Range 38-E	Feet from 288	N/S Line NORTH	Feet from 1650	E/W Line WEST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	-------------------	------------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
		active injector	5-20-2014

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	Puff	N/A	N/A	144	1197
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
☒				

Remarks:

INJECTING AT THIS TIME WTR. GAS. ☒ CO2

Surface puff to D. Production casing would not bleed down completely. Continuous flow. Bled to 10 then started to increase. Shut in well.

FOR RECORD ONLY

Jessie Schaffer

BS 6/24/2014

INITIAL C-103 FOR REPAIRS FILED VIA US POSTAL 5/29/2014

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy.johnson@ony.com	
Date: 5/29/2014	Phone: 806-592-6280
Witness:	

SEP 12 2014

[Handwritten mark]