State of New Mexico

Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

AUG 1 8 280

HOBBS OCD

SEP 1 1 2014 RECEIVED BRADENHEAD TEST REPORT RECEIVED Operator Name 30-025-38078 Manguard Fermian, LLC. Property Name ristmas 28 7. Surface Location UL - Lot Section Township Feet from N/S Line Feet From E/W Line Range County 28 **22** S 330 .eA 37E 1450 Well Status SHUT-IN PRODUCING DATE Well Status 6-4-14 OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH **OBSERVED DATA** If bradenhead flowed water, check all of the descriptions that apply:

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	85			Z8	200
Flow Characteristics					200
Puff	Y / 🔞	Y / N	Y/N	Y / N	
Steady Flow	Y / Q	Y / N	Y/N	Y/N	
Surges	Y / 🚱	Y / N	Y/N	Y/N	
Down to nothing	60/ N	Y / N	Y / N	Y / N	
Gas or Oil	Y / 60	Y / N	Y / N	Y/ N	-
Water	YN	Y / N	Y/N	Y/N	

FRESH CLEAR SALTY SULFUR BLACK Remarks: INJECTING AT THIS TIME _____ WTR, ____ GAS, ___CO2 FOR RECORD ONLY BS 9/12/2014

Signature:	()ill	OIL CONSERVATION DIVISION Entered into RBDMS		
Printed name Michael	ard to			
Title:		Re-test		
E-mail Address:	,			
Date: 6-4-14	Phone: 575-631-0924			
	Witness:			

SEP 1 2 2014