Submit One Copy To Appropriate District Office	State of New Me		Form C-103 Revised August 1, 2011
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO. 30-025-20885
District II 811 S. First St., Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease	
882101220 South St. Francis Dr.District IIISanta Fe, NM 87505		STATE     X     FEE       6. State Oil & Gas Lease No.	
District IV 1220 S. St. Francis Dr., Santa Fe, NM		B-1838-1	
87505 SUNDRY NOTIC	ES AND REPORTS ON WELLS	5	7 - House Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUGOBBS OGD DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Vacuum Glorieta East Unit
1. Type of Well: Oil Well Gas Well Other JUL 2 4 2014			8. Well Number 03
2. Name of Operator ConocoPhillips Company			9. OGRID Number 217817
3. Address of Operator P. O. Box 5	810 Midland, TX 79710	RECEIVED	10. Pool name or Wildcat Vacuum; Glorieta
4. Well Location Unit Letter_E_: 1880 feet from the North line and 660 feet from the West line			
Section       32       Township       17S       Range       35E       NMPM       County       Lea         11.       Elevation (Show whether DR. RKB, RT, GR, etc.)       3967' GL       3967' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🔲 🛛 REMEDIAL WOR			
	CHANGE PLANS	COMMENCE DRI	
OTHER:		│ │ │ │ Location is re	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
Image: Set in the and central nave been inter and reversel. Catholic protection noise nave been property abandoned.         Image: Set in the and central nave been inter and reversel. Catholic protection noise nave been property abandoned.         Image: Set in the and central nave been inter and reversel. Catholic protection noise nave been property abandoned.         Image: Set in the analysis of			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u>			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
<ul> <li>Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.</li> <li>If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with</li> </ul>			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. 🛛 🕅 All metal bolts and other materials have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE_ZHONCK	TITLE Sta	aff Regulatory Tech	DATE 06/25/2014
TYPE OR PRINT NAME <u>Rhonda Ro</u> For State Use Only	gers E-MAIL:	rogerrs@conocopł	nillips.com PHONE: (432)688-9174
APPROVED BY: Malutitala TITLE Compliance Officer DATE 09/17/2014			
Conditions of Approval (if any):			