

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 29 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEURON		API Number 30-025-38786-	
Property Name VACUUM GRAYBURG SAN ANDRES UNIT		Well No. 439 -	

1. Surface Location

UL - Lot B	Section 1	Township 18S	Range 34E	-	Feet from 643	NS Line FNL	Feet From 1632	E/W Line FEL	County LEA
----------------------	---------------------	------------------------	---------------------	---	-------------------------	-----------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	☒ INJ INJECTOR	SWD	OIL	PRODUCER	GAS	DATE 5/15/14
------------------	----	----------------	----	---	-----	-----	----------	-----	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			175	1200
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2 ☒
Steady Flow	Y / N	Y / N	Y / N	☒ Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	☒ Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	☒ Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / ☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(D) CO2 would not bleed down
FAILURE

FOR RECORD ONLY**B8 9/3/2014**

Signature: 		OIL CONSERVATION DIVISION	
Printed name: Dane McCuen		Entered into RBDMS	
Title: Sub Surface Production Specialist		Re-test	
E-mail Address: lmb@chevron.com			
Date: 7/14/14	Phone: 575 942-3526		
Witness:			

SEP 18 2014