

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 16 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CAIEURON	API Number 30-025-33883
Property Name SU BIG BERTHA	Well No. 001

7. Surface Location

UL - Lot F	Section 11	Township 16S	Range 36E	Feet from 2081	N/S Line FNL	Feet From 1870	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL. YES	SHUT-IN NO	INJECTOR INJ	PRODUCER OIL	GAS	DATE 8/15/14
-------------------	---------------	-----------------	-----------------	-----	------------------------


OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0		44	0
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR X
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 9/19/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dane McQueen	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: lennb@chevron.com	
Date: 8/15/14	Phone: 575-942-3526
Witness:	

SEP 22 2014