

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 05 2014

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-38217
Property Name Alie J Boyd 23	Well No. 1

7. Surface Location

UL - Lot C	Section 23	Township 22S	Range 37E	Feet from 405	N/S Line FNL	Feet from 1750	E/W Line FWL	County Lee
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING Pumping	DATE 8/15/2014
-------------------------	---------	-----------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	600			40	95
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

- ① 600 PSI on S.C.
- ② Bled well down in vac truck
- ③ Came back 24 hours later and it was built up to 300 PSI

Failed

BS 9/10/2014

Signature: Justin Hobbs	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: KUV@chevron.com	
Date: 8/15/2014	Phone: 575-631-4228
Witness:	

SEP 22 2014