

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

JUL 24 2014

RECEIVED

BRADENHEAD TEST REPORT

|                                                         |                     |                        |                     |                                                            |                                   |                        |                          |                        |                      |
|---------------------------------------------------------|---------------------|------------------------|---------------------|------------------------------------------------------------|-----------------------------------|------------------------|--------------------------|------------------------|----------------------|
| Operator Name<br><b>CHEURON</b>                         |                     |                        |                     |                                                            | API Number<br><b>30-025-24378</b> |                        |                          |                        |                      |
| Property Name<br><b>VACUUM GRAYBURG SAN ANDRES UNIT</b> |                     |                        |                     |                                                            | Well No.<br><b>015</b>            |                        |                          |                        |                      |
| Surface Location                                        |                     |                        |                     |                                                            |                                   |                        |                          |                        |                      |
| UL - Lot<br><b>5</b>                                    | Section<br><b>2</b> | Township<br><b>18S</b> | Range<br><b>34E</b> | <input checked="" type="checkbox"/>                        | Feet from<br><b>1400</b>          | N/S Line<br><b>FSL</b> | Feet from<br><b>2450</b> | E/W Line<br><b>FEL</b> | County<br><b>LEA</b> |
| Well Status                                             |                     |                        |                     |                                                            |                                   |                        |                          |                        |                      |
| TA'D WELL<br>YES                                        |                     | SHUT-IN<br>NO          |                     | INJECTOR<br><input checked="" type="checkbox"/> <b>INJ</b> |                                   | PRODUCER<br>OIL        |                          | DATE<br><b>5/5/14</b>  |                      |

OBSERVED DATA


|                      | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Csg | (E)Tubing                               |
|----------------------|------------|--------------|--------------|-------------|-----------------------------------------|
| Pressure             | <b>0</b>   |              |              |             | <b>0</b>                                |
| Flow Characteristics |            |              |              |             |                                         |
| Puff                 | Y / N      | Y / N        | Y / N        | Y / N       | CO2 <input type="checkbox"/>            |
| Steady Flow          | Y / N      | Y / N        | Y / N        | Y / N       | WTR <input checked="" type="checkbox"/> |
| Surges               | Y / N      | Y / N        | Y / N        | Y / N       | GAS <input type="checkbox"/>            |
| Down to nothing      | Y / N      | Y / N        | Y / N        | Y / N       | Type of Fluid                           |
| Gas or Oil           | Y / N      | Y / N        | Y / N        | Y / N       | Injected for                            |
| Water                | Y / N      | Y / N        | Y / N        | Y / N       | Waterhead if                            |
|                      |            |              |              |             | applies                                 |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is currently inactive for a well head failure

FOR RECORD ONLY

BS 7/25/2014

|                                                                                                |                            |                           |  |
|------------------------------------------------------------------------------------------------|----------------------------|---------------------------|--|
| Signature:  |                            | OIL CONSERVATION DIVISION |  |
| Printed name: <b>Dane McCuen</b>                                                               |                            | Entered into RBDMS        |  |
| Title: <b>Sub Surface Production Specialist</b>                                                |                            | Re-test                   |  |
| E-mail Address: <b>lnnb@chevron.com</b>                                                        |                            |                           |  |
| Date: <b>7/10/14</b>                                                                           | Phone: <b>575 942-3526</b> |                           |  |
| Witness:                                                                                       |                            |                           |  |

SEP 26 2014

