

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-26790
Property Name CENTRAL VACUUM UNIT	Well No. 146

7. Surface Location

UL - Lot G	Section 31	Township 17S	Range 35E	Feet from 2465	N/S Line N	Feet From 1335	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	-------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING INJECTING	DATE 9/17/2014	
-------------	---------	------------------------	-------------------	--

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0				1345
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ☒ CO2

FOR RECORD ONLY

BS 9/30/2014

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: Artificial Lift and Corrosion Rep	Re-test
E-mail Address: dannyacosta@chevron.com	
Date: 9/24/2014	Phone: 575 631 9033
Witness:	

OCT 01 2014

