

OCT 09 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Linn Operating		API Number 30-025-01467
Property Name Caprock Maljamar Unit		Well No. 2

7. Surface Location

UL - Lot A	Section 18	Township 17-S	Range 33-E	Feet from 10100	N/S Line ENL	Feet from 10100	E/W Line FEH	County Lea
----------------------	----------------------	-------------------------	----------------------	---------------------------	------------------------	---------------------------	------------------------	----------------------

Well Status

TA'D WELL YES	☒ NO ☒ YES	SHUT-IN NO	☒ INJ ☐ SWD	OIL PRODUCER GAS	DATE 10/3/14
------------------	--	---------------	--	---------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / N	Y / N	Y / ☒ N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A&D - had Nothing

This well is S.I. we are waiting on a plugging unit to plug well.

FOR RECORD ONLY

BS 10/10/2014

Signature: D. Sooter	OIL CONSERVATION DIVISION
Printed name: Darren Sooter	Entered into RBDMS
Title: Production Specialist	Re-test
E-mail Address: dsooter@linenergy.com	
Date: 10/3/14	Phone: 575-369-9113
Witness:	

OCT 14 2014