

HOBBS OCD

OCT 08 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <i>McDonnold Operating Inc.</i>		API Number <i>3002511277</i>	
Property Name <i>Langley Jack A 29 #2</i>		Well No. <i>#2</i>	

7. Surface Location

UL - Lot	Section <i>29</i>	Township <i>25S</i>	Range <i>37E</i>	Feet from	N/S Line	Feet From	E/W Line	County <i>Lea</i>
----------	----------------------	------------------------	---------------------	-----------	----------	-----------	----------	----------------------

Well Status

YES	TA'D WELL <i>NO</i>	YES	SHUT-IN <i>NO</i>	INJECTOR <i>INJ</i>	SWD	OIL	PRODUCER	GAS	DATE <i>9/2/14</i>
-----	------------------------	-----	----------------------	------------------------	-----	-----	----------	-----	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	ϕ			ϕ	ϕ
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ☐
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☐
Surges	Y / N	Y / N	Y / N	Y / N	GAS ☐
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 10/8/14

Signature:

Printed name:

Title:

E-mail Address:

Date:

Phone:

Witness:

OIL CONSERVATION DIVISION

Entered into RBDMS

Re-test

OCT 14 2014