

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

OCT 09 2014

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 30-025-25731
Property Name CENTRAL VACUUM UNIT	Well No. 83

7. Surface Location

UL - Lot J	Section 36	Township 17S	Range 34E		Feet from 1330	N/S Line S	Feet From 1330	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	--	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN YES	PRODUCING INJECTION	DATE 9/29/2014
-------------	----------------	------------------------	-------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csng	(E)Tubing
Pressure	0		0	0	1045
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

TEMPORARILY SHUT IN BECAUSE OF NM O STATE 17 WELL
FOR RECORD ONLY

BS 10/10/2014

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: Artificial Lift and Corrosion Rep	Re-test
E-mail Address: dannyacosta@chevron.com	
Date: 9/29/2014	Phone: 575 631 9033
Witness:	

OCT 14 2014