

AUG 28 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Legacy	Operator Name	30025111490000
CJU	Property Name	Well No. 242

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	19	24S	37E	✓	990	N	1587	Lea

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
		WIW	7/25/14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	Q			Q	560
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME	WTR, GAS, CO2
A D Gas		
FOR RECORD ONLY		
BS 10/17/2014		

Signature: Steve Dittman	OIL CONSERVATION DIVISION
Printed name: Steve Dittman	Entered into RBDMS
Title: Prod Tech	Re-test
E-mail Address: sdittman@lesacvlp.com	
Date: 7/25/14	Phone: 432 312 4757
Witness:	

OCT 22