

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 16 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Seely Oil Company		API Number 30-025-011034	
Property Name EK Queen Penrose Unit		Well No. 127	

Surface Location

UL Lot 0	Section 04	Township 18S	Range 33E	Feet from 990	N/S Line S	Feet from 1980	E/W Line E	County Lea
-------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJ INJ	SWD	PRODUCER OIL	GAS	DATE 10/17/2014
------------------	----	----------------	----	------------	-----	-----------------	-----	--------------------

8 AD/OC0.

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	2100
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 10/17/2014

Signature: Shellie Davis	OIL CONSERVATION DIVISION
Printed name: Shellie Davis	Entered into RBDMS
Title: Production Analyst	Re-test
E-mail Address: sdavis@seelyoil.com	
Date: 10/10/2014	Phone: 817-332-1377
Witness: [Signature]	

OCT 27 2014

L