

OCT 21 2014

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 300-25-40060
Property Name New Mexico B NCT-4	Well No. #3

2. Surface Location

UL - Lot C	Section 7	Township 18s	Range 35E	Feet from 990	N/S Line N	Feet From 2225	E/W Line W	County lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8-14
-------------	---------	----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			40	400
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR. ___ GAS, ___ CO2

FOR RECORD ONLY

BS 10/24/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB @ Chevron.com	
Date:	Phone: 575-704-2365
Witness:	

L