

HOBBS OCD

OCT 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	API Number 300-25-40062
Property Name New Mexico B NCT-4	Well No. #5

Surface Location

UL - Lot C	Section 7	Township 18S	Range 35E	Feet from 330	N/S Line N	Feet From 1835	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8-14
-------------	---------	----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csg	(E)Tubing
Pressure	0			40	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR. ___ GAS. ___ CO2

FOR RECORD ONLY

BS 10/24/2014

Signature:  DQKB	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 10-8-14	Phone: 575 - 704 - 2365
Witness:	

