

OCT 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 300-25-40122 ✓
Property Name New Mexico B NCT-4	Well No. #7 ✓

Surface Location

UL - Lot D	Section 7	Township 18S	Range 35E	Feet from 990	N/S Line N	Feet from 490	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8
-------------	---------	----------------	--------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0			40	60
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

FOR RECORD ONLY

BS 10/24/2014

Signature:  DQKB	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 10-8-14	Phone: 575 - 704 - 2365
Witness:	

4