

OCT 21 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 300-25-40462 ✓
Property Name Central Vacuum Unit	Well No. 251 -

2. Surface Location

U/L - Lot A	Section 36	Township 17S	Range 34E	Feet from 704	N/S Line N	Feet from 311	E/W Line E	County Lea
----------------	---------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8-14
-------------	---------	----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	280	280		125	300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:	INJECTING AT THIS TIME ___ WTR. ___ GAS. ___ CO2
Surface & Intermediate blew down to 0 Came back 24 hrs later Surface had 280 lbs and Intermediate had 0 FOR RECORD ONLY BS 10/24/2014	

Signature:	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 10-8-14	Phone: 575 - 704 - 2365
Witness:	

[Handwritten signature]