

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

OCT 21 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	* API Number 300-25-41295
Property Name State AN	Well No. 14

2. Surface Location

UL - Lot N	Section 13	Township 26S	Range 34E	Feet from 330	N/S Line S	Feet From 1345	E/W Line W	County Lea
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING X	DATE 10-8-14
-------------	---------	----------------	-----------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	600			30	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY X	SULFUR	BLACK
-------	-------	---------	--------	-------


Remarks:

INJECTING AT THIS TIME ___ WTR. ___ GAS, ___ CO2

Surface casing blew produced water + gas. Blew down to 0
Came back in 24 hrs. Surface had 80 lbs. gas only took 5 sec. to blow down.

FOR RECORD ONLY

BS 10/24/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Daniel Pace	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: DQKB@chevron.com	
Date: 10-8-14	Phone: 575 - 704 - 2365
Witness:	

OCT 30 2014

