

Form No. 1 (Rev. 10/1/03)
 5010-107-01-1010 (10/03)

HOBBS OCD

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

OCT 31 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name <u>Chevron</u>				API Number <u>3002512349</u>					
Property Name <u>West Dollarnide Drivewad Unit</u>				Well No. <u>56</u>					
Surface Location									
UT - Lot <u>E</u>	Section <u>6028</u>	Township <u>33</u>	Range <u>5024</u>	Section <u>230</u>	North <u>N</u>	Section <u>330</u>	East <u>W</u>	County <u>Lea</u>	

Well Status

YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PRODUCING		SHUT-IN		INJECTOR		SWD		OIL		GAS	
DATE <u>10/28/2014</u>											

OBSERVED DATA

	Pressure	Flow Characteristics	Flow Characteristics	Flow Characteristics	Flow Characteristics	Flow Characteristics
Pressure	0	0	0	0	0	1000
Flow Characteristics						
Flow	Y N	Y N	Y N	Y N	Y N	CO2
Steady Flow	Y N	Y N	Y N	Y N	Y N	WTR
Burge	Y N	Y N	Y N	Y N	Y N	GAS
Down to Bottom	Y N	Y N	Y N	Y N	Y N	Flow Test
Gas or Oil	Y N	Y N	Y N	Y N	Y N	Flow Test
Water	Y N	Y N	Y N	Y N	Y N	Flow Test

Remarks - Flow test for each string. Also, other pertinent information regarding well down or up or any other well up or down.

FOR RECORD ONLY

Signature <u>Chris Hylton</u>		OIL CONSERVATION DIVISION	
Print Name <u>Chris Hylton</u>		Email <u>CHYLTON@EDOS</u>	
Title <u>FSA</u>		Request	
Email Address <u>ETM@Chevron.com</u>			
Date <u>10/28/14</u>	Phone <u>432-266-1402</u>		

OCT 31 2014