

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

NOV 05 2014

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: ConocoPhillips	Contact: Spencer Cluff
Address: 29 Vacuum Complex Lane	Telephone No. 575-391-3143
Facility Name: EVGSAU 2622-004	Facility Type: Satellite
Surface Owner: NMOCD	Mineral Owner: NMOCD
API No. 30-025-26395	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	26	17S	35E	2496	North	1544	West	LEA

Latitude **32.8057498009579** Longitude **103.446081589692**

NATURE OF RELEASE

Type of Release: Fire	Volume of Release: 0	Volume Recovered: 0
Source of Release: NA	Date and Hour of Occurrence 11/04/2014 10:00 am	Date and Hour of Discovery 11/04/14 2:45 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Spencer Cluff	Date and Hour: 11/05/2014 10:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On November 4, 2014 at approximately 1000 hrs. MST a fire occurred at the EVGSAU 2622-004. COPC employee was setting a well and noticed that a meter base was arcing. The meter flashed and blew the fuses which resulted in a loss of power. The fault clearing caused the arc flash to self-extinguish. COPC employee called COPC Systems Specialist to inform him of the incident. I&E replaced the equipment. The NM Electrical inspector will verify the replacement and Lea County Electric will return to service. There were no injuries associated with this incident.

Describe Area Affected and Cleanup Action Taken.*

None of the area was affected by the fire. I&E replaced the equipment. The NM Electrical inspector will verify the replacement and Lea County Electric will return to service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Spencer A. Cluff</i>	OIL CONSERVATION DIVISION	
Printed Name: Spencer Cluff	Approved by Environmental Specialist:	
Title: LEAD HSE	Approval Date: 11-5-14	Expiration Date: _____
E-mail Address: spencer.a.cluff@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/05/2014	Phone: 575-391-3143	

* Attach Additional Sheets If Necessary

NOV 10 2014