

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 06 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CASO Petroleum of New Mexico		API Number 30005105040000
Property Name CSAU		Well No. 20

Surface Location

Tr. Lot D	Section 11	Township 8S	Range 30E	Feet from 660	N/S Line N	Feet from 660	E/W Line W	County Chavez
---------------------	----------------------	-----------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-------------------------

Well Status

TA'D WELL YES	SHUT-IN NO	INJECTOR INJ	SWD NO	OIL PRODUCER	GAS NO	DATE 9/2/14
-------------------------	----------------------	------------------------	------------------	------------------------	------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm.1	(C)Interm.2	(D)Prod. Casing	(E)Tubing
Pressure	0				1100
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS -
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid expected for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 11/17/2014

Signature: Robert McKenzie	OIL CONSERVATION DIVISION
Printed name: Robert McKenzie	Entered into RBDMS
Title: SR. Field Ops Mgr.	Re-test
E-mail Address: Robert.McKenzie@nmservice.com	
Date: 9/2/14	Phone: 432-425-3150
Witness	

NOV 12 2014

h.