

NOV 06 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CASO Petroleum of New Mexico	API Number 30005105790000
Property Name CSAU	Well No. 56

Surface Location

UT - East M	Section 11	Township 8S	Range 30E	Feet from 660	NS Line 3	Feet from 660	E/W Line W	County CRAVES
-----------------------	----------------------	-----------------------	---------------------	-------------------------	---------------------	-------------------------	----------------------	-------------------------

Well Status

TA'D WELL YES	NO	SHUT-IN YES	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 9/2/14
------------------	----	----------------	----	------------------------	-----	-----------------	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intermit (1)	(C) Intermit (2)	(D) Prod Casing	(E) Tubing
Pressure	0				1200
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Unpacked for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead of

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

BS 11/7/2014

Signature: Robert McKenzie	OIL CONSERVATION DIVISION
Printed name: Robert McKenzie	Entered into RBDMS
Title: SR. Field Ops Mgr	Re-test
E-mail Address: robert.mckenzie@nrgiservices.com	
Date: 9/2/14	Phone: 432-425-3100
Witness:	

NOV 12 2014