

NOV 06 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CANCO Petroleum of New Mexico	API Number 30005202240000
Property Name C.SAN	Well No 178

Surface Location

U.L. - Lot	Section 34	Township 8S	Range 30E	Feet from 660	NS Line S	Feet from 660	E/W Line W	County CHAVEZ
------------	----------------------	-----------------------	---------------------	-------------------------	---------------------	-------------------------	----------------------	-------------------------

Well Status

YES	YES	YES	NO	YES	NO	YES	NO	YES	NO	DATE 9/2/14
-----	-----	-----	----	-----	----	-----	----	-----	----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intermit 1	(C) Intermit 2	(D) Prod. Casing	(E) Tubing
Pressure	3				No tubing
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Impurities
Water	Y/N	Y/N	Y/N	Y/N	Water level of

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

B8 11/7/2014

Signature Robert McKenzie	OIL CONSERVATION DIVISION
Printed name Robert McKenzie	Entered into RBDMS
Title SR. Field Ops Mgr.	Re-test
E-mail Address Robert.McKenzie@nmsr.com	
Date 9/2/14	Phone 532-425-3150
Witness	

NOV 12 2014

L