

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

NOV 06 2014

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CANO Petroleum of New Mexico		30005/20529		20529
Property Name CSAU		Well No 200		

Surface Location

U.L. - Lot	Section	Township	Range	Feet from	NS Line	Feet from	EAS Line	County
	6	9S	30E	990	S	330	E	CHAVEZ

Well Status

TA'D WELL ☒ YES	SHUT-IN ☒ YES	NO	INJECTOR ☒ YES	SWD	OIL	PRODUCER ☒ YES	GAS	DATE 9/2/14
--	--	----	---	-----	-----	---	-----	-----------------------

OBSERVED DATA

	(A) Surface	(B) Intermit 1	(C) Intermit 2	(D) Prod Casing	(E) Tubing
Pressure	0				no tubing
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Impound for
Water	Y/N	Y/N	Y/N	Y/N	Water level of

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

B8 11/7/2014

Signature: Robert McKenzie	OIL CONSERVATION DIVISION
Printed name: Robert McKenzie	Entered into RBDMS
Title: SR. Field Ops Mgr	Re-test
E-mail Address: robert.mckenzie@NM1-service.co	
Date: 9/2/14	Phone: 432-425-3150
Witness:	

NOV 18 2014

h