

NOV 19 2014

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

|                                      |                          |
|--------------------------------------|--------------------------|
| Operator Name<br>CHEVRON             | API Number<br>3002540470 |
| Property Name<br>Central Vacuum Unit | Well No.<br>366          |

2. Surface Location

|               |               |                 |              |                   |               |                  |               |               |
|---------------|---------------|-----------------|--------------|-------------------|---------------|------------------|---------------|---------------|
| UL - Lot<br>H | Section<br>36 | Township<br>17S | Range<br>34E | Feet from<br>1855 | N/S Line<br>N | Feet From<br>855 | E/W Line<br>E | County<br>Lea |
|---------------|---------------|-----------------|--------------|-------------------|---------------|------------------|---------------|---------------|

Well Status

|             |         |           |                    |
|-------------|---------|-----------|--------------------|
| Well Status | SHUT-IN | PRODUCING | DATE<br>11-12-2014 |
|-------------|---------|-----------|--------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A)Surf-Interm | (B)Interm(1)-Interm(2) | (C)Interm-Prod | (D)Prod Csg | (E)Tubing |
|----------------------|----------------|------------------------|----------------|-------------|-----------|
| Pressure             | 0              | —                      | 440            | 130         | 370       |
| Flow Characteristics |                |                        |                |             |           |
| Puff                 | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Steady Flow          | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Surges               | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Down to nothing      | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Gas or Oil           | Y / N          | Y / N                  | Y / N          | Y / N       |           |
| Water                | Y / N          | Y / N                  | Y / N          | Y / N       |           |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|


Remarks:

Blew Intermediate down to Ops  
Using Vac truck came back 24 hrs  
later and checked pressure. pressure was 0.

INJECTING AT THIS TIME \_\_\_ WTR. \_\_\_ GAS. \_\_\_ CO2

FOR RECORD ONLY

BS 11/20/2014

|                                                                                                |                           |
|------------------------------------------------------------------------------------------------|---------------------------|
| Signature:  | OIL CONSERVATION DIVISION |
| Printed name: Daniel Pace                                                                      | Entered into RBDMS        |
| Title: FSA                                                                                     | Re-test                   |
| E-mail Address: DQKB@chevron.com                                                               |                           |
| Date: 11-9-14                                                                                  | Phone: (575) 704 - 2365   |
| Witness:                                                                                       |                           |

NOV 25 2014