

NOV 25 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Oxy USA	API Number 30-025-055340000
Property Name EAST EUMONT	Well No. 4

7. Surface Location

UL - Lot K	Section 33	Township 18S	Range 37E	Feet from 1980	N/S Line S	Feet from 1980	E/W Line W	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status Active	SHUT-IN	PRODUCING Injector (Active)	DATE 4/15/14	Water injection
------------------------------	---------	---------------------------------------	------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0.750			800 psi	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR ☒	FRESH ☒	SALTY ☐	SULFUR ☐	BLACK ☐
---	---	--------------------------------	---------------------------------	--------------------------------

Remarks:

Opened (B) to vacuum truck well flowed for 5 min
Recovered 1 barrel of fresh water then flow died

FOR RECORD ONLY

B2 11/26/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Alex Estrella	Entered into RBDMS
Title: Production Tech	Re-test
E-mail Address: alex-estrella@oxy.com	
Date: 4-15-14	
Phone: 575-310-9889	
Witness:	

DEC 02 2014