

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 03 2014

BRADENHEAD TEST REPORT

Operator Name McGOWAN WORKING PARTNERS INC.	API Number 30025022140000	RECEIVED
Property Name STATE 35 UNIT	Well No. 003	

* Surface Location									
UL Loc A	Section 35	Township 17-S	Range 34-E	Eastings 660	NS Line N	Feet From 660	EW Line E	County Lea	

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	DATE 8-19-2014

OBSERVED DATA

	(A) Surface	(B) Depth (1)	(C) Depth (2)	(D) Prod (Csg)	(E) Volume
Pressure	0	0		35	35
Flow Characteristics					
Full	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR —
Surge	Y/N	Y/N	Y/N	Y/N	GAS —
Down to working	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Leakage
Water	Y/N	Y/N	Y/N	Y/N	Whether it

Remarks: — Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or conditions build up if applies.

FOR RECORD ONLY

Signature: Jack Steunson	OIL CONSERVATION DIVISION
Printed name: Jack Steunson	Entered into RBDMS
Title: PUMP	Re-test
E-mail Address:	
Date: 8-19-2014	Phone: 575-631-1083
Witness:	

Bill Semanuel
OCD

DEC 03 2014