State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

NOV 2 5 2014

	BRADENHEAD TEST REPORT			RECEIVED			
/	Operator Name				30-025-098780000 Well No.		
	0xy 1	Property Name		150-025	-4987	80000	
	East	Eumont			1	D Car No.	
		7. Surface Location)n				
	ownship Range	Feet from	N/S Line	Feet From	E/W Line	County	
E 13 11	95 37E	L 12091		(CO)	<u> </u>	lea	
/.		Well Status					
Well Status	SHUT-IN	PRODUCING		DATE			
ONEN		· · · · · · · · · · · · · · · · · · ·	CF.Je)				
OPEN I	BRADENHEAD AND IN	TERMEDIATE TO ATMOSPHE		FOR 15 MINUT	ES EACH		
If bradenhead flowed water,	check all of the description	OBSERVED DA' ons that apply:	ГА		L		
	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Pro	d Csng	(E)Tubing	
Pressure	005:) kg	0	
Flow Characteristics	100				/P/	\vdash	
Puff	Y / 🕸 _	Y/N	Y/N		P/N	1	
Steady Flow	Y/8	Y/N	Y/N		Y780		
Surges	Y / 🔊	Y/N	Y/N		Y/B		
Down to nothing	Y / Ø	Y/N	Y7 N		Y / 189		
Gas or Oil Water	Y / 30	Y/N Y/N	Y/N Y/N		Y / Ø		
CLEAR	FRESH	SALTY	SULFU		BLACK		
Remarks:					11.11	\	
					Wang	injection	
					•		
						·	
				or rec	ann O	MLY	
				end Rec	OME -	-	
,			LO	A B B B B			
			BS				
Signature: //			<i>fs</i> }				
Signature:			BB			NOISIVID N	
Signature: A CX	Esheile		1/2		ISERVATIO		
	Esheile CshrcMay	Dxy.com	1/2	OIL CON	ISERVATIO		
Printed name: ACX	Esheile Cshrcine a) i	<u> </u>		OIL CON	ISERVATIO		
Printed name: PKX Title: CKX	Eshelle CShrc/Mca/E	DXY-COM 575-390 -988°		OIL CON	ISERVATIO		
Printed name: A CX Title: CMCX = E-mail Address:	eshemed a	<u> </u>		OIL CON	ISERVATIO		