

NOV 25 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Oxy USA, Inc.	* API Number 30-025-31071
Property Name State Brw	Well No. #5 Injection

2. Surface Location

UL - Lot K	Section 14	Township 10 S	Range R 32 E	Feet from 1410	N/S Line S	Feet From 1405	E/W Line W	County Lea
----------------------	----------------------	-------------------------	------------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status	SHUT-IN No	PRODUCING Injection	DATE 6-16-14
-------------	----------------------	-------------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1) Interm (2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	like surface water 5 lbs	none x	none x	2 lbs	200 lbs
Flow Characteristics	pure - 5 seconds	none	none	Just puff	2 seconds
Pull	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ☒	FRESH ☒	SALTY ☐	SULFUR ☐	BLACK ☐
---	---	--------------------------------	---------------------------------	--------------------------------

Remarks:

1410 FSL
1405 FWL
Sec. 14. T10S. R32E.
Lea County N.M.

replaced all 2" valves on Interm
and casing after test was done.

FOR RECORD ONLY

QAD/bcd

Signature: Dale Boland	OIL CONSERVATION DIVISION
Printed name: Dale Boland	Entered into RBDMS
Title: Lease Operator	Re-test
E-mail Address: DLBoland@oxy.com	
Date: 6-16-14	Phone: 575-631-5375
Witness: Jose Candia	

631-0810

DEC 03 2014