

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 03 2014

RECEIVED

BRADENHEAD TEST REPORT

Operator Name DC Energy LLC	API Number 30-025-24287
Property Name Crosby Deep	Well No. 2

Surface Location

U/L - Lot 6	Section 33	Township 25S	Range 37E	Feet from 1650	N/S Line N	Feet from 2310	E/W Line E	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

PROD WELL ☒ YES	NO	SHUT-IN ☒ YES	NO	INJ	SWD	OIL	PRODUCER	GAS	DATE 11/25/2014
--	----	--	----	-----	-----	-----	----------	-----	---------------------------

OBSERVED DATA

	(A) Surface	(B) Intercom 1	(C) Intercom 2	(D) Prod. Casing	(E) Tubing
Pressure	ϕ	ϕ		ϕ	ϕ
Flow Characteristics					
Puff	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	CO2 ☐
Steady Flow	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	WTR ☐
Surges	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	GAS ☐
Down to nothing	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	Type of fluid Injected for Waterflood if applicable
Gas or Oil	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	
Water	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	☒ Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

FOR RECORD ONLY

SAN/OCD

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 11/25/2014	Phone:
Witness:	

DEC 04 2014