

HOBBS OGD

DEC 11 2014

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON					API Number 3002535563				
Property Name Vacuum Grayburg San Andres Unit					Well No. 249				
Surface Location									
UL - Lot F	Section 01	Township 18S	Range 34E	✓	Feet from 1390	N/S Line N	Feet from 2530	E/W Line W	County Lea

Well Status

Well Status	SHUT-IN X	PRODUCING	DATE 11-19-14
-------------	--------------	-----------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0		100	500	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	0 / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	0 / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:


INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Well is Hard Shut in after last BH Failure
Has oil on production casing.

FOR RECORD ONLY

Came back 24 hours later Intermediate had 0 psi

Failed between 5/2014
BS 12/12/2014

Signature:  DQKB		OIL CONSERVATION DIVISION	
Printed name: Daniel Pace		Entered into RBDMS	
Title: FSA		Re-test	
E-mail Address: DQKB@chevron.com			
Date: 11/19-14	Phone: (575) 704 - 2365		
Witness:			

DEC 15 2014